

Troubleshooting Thermoforming Problems

INTRODUCTION

The most common problem in thermoforming KYDEX® thermoplastic sheet is one of trying to heat KYDEX® sheet too quickly. See our technical brief on ideal thermoforming conditions. If a problem still exists, review the troubleshooting section of this brief.

TROUBLESHOOTING

Problems	Causes	Remedies
Blister or Bubbles	Heating too Quickly	<ol style="list-style-type: none"> 1. Lower heater(s) temperatures. 2. Use slower heating. 3. Increase distance between heaters and sheet.
	Excessive Moisture	<ol style="list-style-type: none"> 1. Pre-dry material. 2. Heat material from both sides. 3. Lower heater(s) temperatures (more soak time).
	Uneven Heating	<ol style="list-style-type: none"> 1. Hot spots (install screening to deflect heat from overheated areas). 2. Check heaters for proper operation. 3. Adjust heater zones to balance sheet surface temperature.
Poor Detail in Formed Part	Sheet too cold	<ol style="list-style-type: none"> 1. Increase dwell time to heat sheet longer. 2. Increase temperature of heaters. 3. Increase size of vacuum holes. 4. Check for vacuum leaks.
	Insufficient Vacuum	<ol style="list-style-type: none"> 1. Check vacuum holes for blockages. 2. Increase the number of vacuum holes. 3. Increase size of vacuum holes. 4. Check for vacuum leaks.



Customer Collaboration
 6685 Low St, Bloomsburg, PA 17815 USA
 Phone: 800.325.3133, +1.570.389.5810
 Email: info@kydex.com

appLab™
 Phone: 800.682.8758
 Email: applab@kydex.com

kydex.com

Troubleshooting Thermoforming Problems

TROUBLESHOOTING

Problems	Causes	Remedies
Poor Detail in Part	Vacuum not drawing fast enough	<ol style="list-style-type: none"> 1. Check the vacuum gauge for minimum of in. /Hg pressure. 2. Check for vacuum leaks. 3. Use slots instead of vacuum holes. 4. Increase the size of the vacuum surge tank or vacuum capacity. 5. Check vacuum hose for leaks or collapse.
Poor Detail in Formed Part (when pressure forming)	Improper pressure	<ol style="list-style-type: none"> 1. Use 20 - 50 psi (.137 - .345 Mpa) air pressure.
Sheet Scorched	Surface of the sheet too hot	<ol style="list-style-type: none"> 1. Reduce heating cycle (dwell time). 2. Lower heater(s) temperature (more soak time).
Blushing or Discoloration	Excessive Heat	<ol style="list-style-type: none"> 1. Reduce cycle time (poor detail may occur due to material being too cold). 2. Reduce heater temperatures (increasing dwell time may be required). 3. If problems exist in one area only, check heaters.
Whitening of Part in Corners	Sheet too Cold	<ol style="list-style-type: none"> 1. Increase the dwell time. 2. Reduce platen time delay. 3. Reduce vacuum delay.
Webbing, Bridging or Wrinkling	Sheet too Hot	<ol style="list-style-type: none"> 1. Reduce heating time. 2. Lower heater(s) temperatures.
	Insufficient Vacuum	<ol style="list-style-type: none"> 1. Check mold for proper vacuum. 2. Check vacuum lines for restrictions.
	Excessive Draw Ratio or Poor Mold Design	<ol style="list-style-type: none"> 1. Redesign mold. 2. Increase the draft and radii of the mold design. 3. Use a plug assist. 4. Add take-up blocks (web catchers) to pull material away from the corners. 5. Use recessed pockets (web moats) in web areas. 6. If tooling is multiple mold design, increase the distance between molds.



Customer Collaboration
 6685 Low St, Bloomsburg, PA 17815 USA
 Phone: 800.325.3133, +1.570.389.5810
 Email: info@kydex.com

appLab™
 Phone: 800.682.8758
 Email: applab@kydex.com

kydex.com

Troubleshooting Thermoforming Problems

TROUBLESHOOTING

Problems	Causes	Remedies
Nipples on Mold Side of Formed Part	Sheet too Hot	<ol style="list-style-type: none"> 1. Reduce dwell time. 2. Reduce heater(s) temperatures.
	Vacuum Holes	<ol style="list-style-type: none"> 1. Plug vacuum holes and re-drill with smaller bit.
Excessive Sag After Heating	Sheet too Hot	<ol style="list-style-type: none"> 1. Reduce dwell time. 2. Reduce heater(s) temperatures. 3. Balance sheet surface temperature (increase the perimeter heat and lower center heat).
Chill Marks or “Mark-Off Lines”	Mold Temperature too cold	<ol style="list-style-type: none"> 1. Increase the mold temperature (do not excess 165°C) if the mold is water cooled. If the mold is not temperature controlled, pre-heat the mold with a torch. 2. Increase the pre-stretch to allow the mold to come in contact with the material later.
	Plug Assist Cold	<ol style="list-style-type: none"> 1. Use a syntactic foam plug assist. 2. Cover plug assist with flannel or felt.
	Sheet too Hot	<ol style="list-style-type: none"> 1. Reduce dwell time. 2. Reduce heater(s) temperatures.
Surface imperfections	Pock Marks on Smooth Mold Surface	<ol style="list-style-type: none"> 1. Air entrapment (sand blast mold texture with #30 shot grit).
	Dirt on Sheet or Mold	<ol style="list-style-type: none"> 1. Clean sheet and/or mold surface prior to forming.
Shiny Streaks or Spots	Sheet Overheated in Areas	<ol style="list-style-type: none"> 1. Adjust heaters in affected areas. 2. Hot spots (screen areas to deflect heat, if unable to do with zoning).
Distortion in Part after Removing Part from the Mold	Removing Part From Mold too Soon	<ol style="list-style-type: none"> 1. Increasing the cooling cycle. 2. Use temperature controlled mold. 3. Use fans or water mist.
	Uneven Cooling	<ol style="list-style-type: none"> 1. Cool part evenly by adding additional water coolings to mold and/or add fans. 2. Poor Material distribution (improve pre-stretch or plug assist).



Customer Collaboration
 6685 Low St, Bloomsburg, PA 17815 USA
 Phone: 800.325.3133, +1.570.389.5810
 Email: info@kydex.com

appLab™
 Phone: 800.682.8758
 Email: applab@kydex.com

kydex.com

Troubleshooting Thermoforming Problems

TROUBLESHOOTING

Problems	Causes	Remedies
Poor Wall Thickness Distribution	Improper Sag	<ol style="list-style-type: none"> Heat sheet uniformly to allow material to flow properly. Mount mold on top platen. Use Billow Vacuum Snap-Back method. Use plug assist.
	Hot or Cold Spots in sheet	<ol style="list-style-type: none"> Balance sheet heating. Check heaters for proper operation. Avoid air flow and drafts across sheet.
	Mold Too Cold	<ol style="list-style-type: none"> Increase mold temperature 10° below HDT of material.
Shrink Marks in Corners	Poor Vacuum	<ol style="list-style-type: none"> Check for vacuum leaks. Check vacuum holes for blockages. Add vacuum holes. Increase the vacuum time to hold material tight to mold until material is cooled below HDT.
Thin Corners when Forming over a Female Tool	Improper Forming Techniques	<ol style="list-style-type: none"> Use a Billow Forming technique. This will help by pre-stretching the sheet before forming. Use a plug assist.
	Variation in Sheet Temperature	<ol style="list-style-type: none"> Adjust the heating temperatures so the sheet is heated evenly. Increase the perimeter (outer) heaters approximately 10% higher than the center.
Part Sticking to Mold	Mold Design	<ol style="list-style-type: none"> Increase the draft angle of the mold. Sand blast the mold with #30 grit to roughen the surface of the mold. Use breakaway mold for undercuts. Increase the air ejection pressure. Use a mold release agent (silicone, talc, etc.)
Tearing of the Sheet When Forming	Mold Design	<ol style="list-style-type: none"> Increase the radius in the corners.
	Sheet too Cold	<ol style="list-style-type: none"> Increase heating cycle and temperatures. Balance temperature across sheet.
	Vacuum Too Rapid	<ol style="list-style-type: none"> Reduce the rate (speed) of the vacuum being pulled.



Customer Collaboration
 6685 Low St, Bloomsburg, PA 17815 USA
 Phone: 800.325.3133, +1.570.389.5810
 Email: info@kydex.com

applab™
 Phone: 800.682.8758
 Email: applab@kydex.com

kydex.com

Because we cannot anticipate or control the many different conditions under which this information and our products may be used, we do not guarantee the applicability of the accuracy of this information or the suitability of our products in any given situation. Users should conduct their own tests to determine the suitability of each product for their particular purposes. Data in the physical property table represents typical values and are to serve only as a guide for engineering design. Results are obtained from specimens under ideal laboratory conditions. Right to change physical properties as a result of technical progress is reserved. THE PRODUCTS DISCUSSED ARE SOLD WITHOUT WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE, EITHER EXPRESSED OR IMPLIED, EXCEPT AS PROVIDED IN OUR STANDARD TERMS AND CONDITIONS OF SALE. Buyer assumes all responsibility for loss or damage arising from the handling and use of our products, whether done in accordance with directions or not. In no event shall the supplier or the manufacturer be liable for incidental or consequential damages. Also, statements concerning the possible use of our products are not intended as recommendations to use our products in the infringement of any patent. Consult local code and regulatory agencies for specific requirements regarding code compliance, transporting, processing, recycling and disposal of our product. Texture, product grade and other conditions may cause variations in appearance.

This information supersedes all previously published data.